

FIG. 1









FIG. 2



















## REPLACEMENT SHEET











## REPLACEMENT SHEET

6/6

mode			L*			<b>p</b> *
(passes)	K	ວ	Я	υ	Ħ	¥
	0.224	0.538	0.483	1.064	0.770	0.652
	0.101	0.562		1.157	0.759	0.719
4, 8 or 12	0.233	0.561	0.465	1.064	0.762	0.664
	0.145	0.563	0.472	1.124	0.763	0.679
	0.063	0.535	0.481	1.124	0.753	0.691
4 or 8	0.055	0.552	0.484	1.126	0.749	0.710
12	0.002	0.433	0.401	1.116	0.667	0.609
				K C   0.224 0.538   0.101 0.562   0.233 0.561   0.145 0.563   0.063 0.552   0.055 0.552   0.002 0.433	K C   0.224 0.538   0.101 0.562   0.233 0.561   0.145 0.563   0.063 0.535   0.055 0.552   0.002 0.433	K   C   H   C   0.224   0.538   0.483   1.064   0.024   0.562   0.508   1.157   0.023     0.101   0.562   0.508   1.157   0.023   0.561   0.465   1.064   0.023     0.145   0.563   0.472   1.124   0.005   0.481   1.126   0.000     0.055   0.552   0.484   1.126   0.000   0.433   0.401   1.116   0.000

F1G. 1